

Cornice dropped in Slats and propagated slab at a weak layer of facets around 70cm height from ground. Dug a snow pit of 140cm and got etc results on the same layer ECTP26 stubborn but holds a large consequence. Photo: Z. Bailey

Advisory Region
Northern Madison

Longitude
-111.38W
Latitude
45.17N
Avalanche Details: Cornice Triggered Avalanche Buck Ridge
Northern Madison, 2022-12-10